

Software provided by the Coalition for Quality Care / Compiled by Voices for Quality Care

Data: Source: Center for Medicare & Medicaid Services Nursing Home Compare Download Valid 12/1/2015

prov num	Provname	address	state	zip	survey date output	Survey Type	def pref	tag	scope	defstat	statdate	cycle	standard	complaint	
Homes: 7		DC													
Sets: 1	BRIDGEPOINT SUB-ACUTE AND REHAB CAPITOL HILL	DC													
95027	BRIDGEPOINT SUB-ACUTE AND REHAB CAPITOL HILL	700 CONSTITUTION AVE. NE	DC	20002	8/11/14	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	9/15/14	1	Y	N
95027	BRIDGEPOINT SUB-ACUTE AND REHAB CAPITOL HILL	700 CONSTITUTION AVE. NE	DC	20002	7/30/13	Fire Safety	K	18	Corridor and hallway doors that block smoke.	C	Deficient, Provider has date of correction	10/7/13	2	Y	N
95027	BRIDGEPOINT SUB-ACUTE AND REHAB CAPITOL HILL	700 CONSTITUTION AVE. NE	DC	20002	9/6/12	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	10/11/12	3	Y	N
Sets: 1	BRINTON WOODS HEALTH & REHAB OF WASHINGTON DC	DC													
95015	BRINTON WOODS HEALTH & REHAB OF WASHINGTON DC	1380 SOUTHERN AVE SE	DC	20032	7/16/15	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	E	Deficient, Provider has date of correction	9/18/15	1	Y	N
95015	BRINTON WOODS HEALTH & REHAB OF WASHINGTON DC	1380 SOUTHERN AVE SE	DC	20032	9/9/14	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	D	Deficient, Provider has date of correction	10/15/14	2	Y	N
95015	BRINTON WOODS HEALTH & REHAB OF WASHINGTON DC	1380 SOUTHERN AVE SE	DC	20032	9/18/13	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	D	Deficient, Provider has date of correction	12/9/13	3	Y	N
Sets: 2	CARROLL MANOR NURSING & REHAB	DC													
95034	CARROLL MANOR NURSING & REHAB	725 BUCHANAN ST., NE	DC	20017	9/9/15	Fire Safety	K	62	Automatic sprinkler systems that have been maintained in working order.	F	Deficient, Provider has date of correction	11/19/15	1	Y	N
95034	CARROLL MANOR NURSING & REHAB	725 BUCHANAN ST., NE	DC	20017	10/7/14	Fire Safety	K	62	Automatic sprinkler systems that have been maintained in working order.	E	Deficient, Provider has date of correction	11/13/14	2	Y	N
95034	CARROLL MANOR NURSING & REHAB	725 BUCHANAN ST., NE	DC	20017	9/26/13	Fire Safety	K	62	Automatic sprinkler systems that have been maintained in working order.	E	Deficient, Provider has date of correction	10/16/13	3	Y	N
95034	CARROLL MANOR NURSING & REHAB	725 BUCHANAN ST., NE	DC	20017	9/9/15	Fire Safety	K	130	Other fire safety features required by fire safety codes.	E	Deficient, Provider has date of correction	11/19/15	1	Y	N
95034	CARROLL MANOR NURSING & REHAB	725 BUCHANAN ST., NE	DC	20017	10/7/14	Fire Safety	K	130	Other fire safety features required by fire safety codes.	E	Deficient, Provider has date of correction	11/13/14	2	Y	N
95034	CARROLL MANOR NURSING & REHAB	725 BUCHANAN ST., NE	DC	20017	9/26/13	Fire Safety	K	130	Other fire safety features required by fire safety codes.	D	Deficient, Provider has date of correction	10/16/13	3	Y	N

DEANWOOD REHABILITATION AND WELLNESS															
DC															
Sets: 2	DEANWOOD REHABILITATION AND WELLNESS CENTER	5000 BURROUGHS AVE. NE	DC	20019	2/12/15	Fire Safety	K	18	Corridor and hallway doors that block smoke.	E	Deficient, Provider has date of correction	4/14/15	1	Y	N
95019	DEANWOOD REHABILITATION AND WELLNESS CENTER	5000 BURROUGHS AVE. NE	DC	20019	2/25/14	Fire Safety	K	18	Corridor and hallway doors that block smoke.	E	Deficient, Provider has date of correction	5/2/14	2	Y	N
95019	DEANWOOD REHABILITATION AND WELLNESS CENTER	5000 BURROUGHS AVE. NE	DC	20019	3/27/13	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	5/9/13	3	Y	N
95019	DEANWOOD REHABILITATION AND WELLNESS CENTER	5000 BURROUGHS AVE. NE	DC	20019	2/12/15	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	D	Deficient, Provider has date of correction	4/14/15	1	Y	N
95019	DEANWOOD REHABILITATION AND WELLNESS CENTER	5000 BURROUGHS AVE. NE	DC	20019	2/25/14	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	E	Deficient, Provider has date of correction	5/2/14	2	Y	N
95019	DEANWOOD REHABILITATION AND WELLNESS CENTER	5000 BURROUGHS AVE. NE	DC	20019	3/27/13	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	D	Deficient, Provider has date of correction	5/9/13	3	Y	N
HEALTH & REHABILITATION CENTER AT THOMAS CIRCLE															
Sets: 1	DC														
95021	HEALTH & REHABILITATION CENTER AT THOMAS CIRCLE	1330 MASSACHUSETTS AVENUE NW	DC	20005	8/27/15	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	10/2/15	1	Y	N
95021	HEALTH & REHABILITATION CENTER AT THOMAS CIRCLE	1330 MASSACHUSETTS AVENUE NW	DC	20005	6/5/14	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	8/18/14	2	Y	N
95021	HEALTH & REHABILITATION CENTER AT THOMAS CIRCLE	1330 MASSACHUSETTS AVENUE NW	DC	20005	6/13/13	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has no plan of correction		3	Y	N
INGLESIDE AT ROCK CREEK															
Sets: 2	DC														
95028	INGLESIDE AT ROCK CREEK	3050 MILITARY ROAD NW	DC	20015	8/31/15	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	10/16/15	1	Y	N
95028	INGLESIDE AT ROCK CREEK	3050 MILITARY ROAD NW	DC	20015	9/8/14	Fire Safety	K	18	Corridor and hallway doors that block smoke.	D	Deficient, Provider has date of correction	10/21/14	2	Y	N
95028	INGLESIDE AT ROCK CREEK	3050 MILITARY ROAD NW	DC	20015	6/20/13	Fire Safety	K	18	Corridor and hallway doors that block smoke.	E	Deficient, Provider has date of correction	8/9/13	3	Y	N
95028	INGLESIDE AT ROCK CREEK	3050 MILITARY ROAD NW	DC	20015	8/31/15	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	D	Deficient, Provider has date of correction	10/16/15	1	Y	N

95028	INGLESIDE AT ROCK CREEK	3050 MILITARY ROAD NW	DC	20015	9/8/14	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	D	Deficient, Provider has date of correction	10/21/14	2	Y	N
95028	INGLESIDE AT ROCK CREEK	3050 MILITARY ROAD NW	DC	20015	6/20/13	Fire Safety	K	25	Walls that prevent smoke from passing through and would resist fire for at least one hour.	E	Deficient, Provider has date of correction	8/9/13	3	Y	N
Sets: 1	TRANSITIONS HEALTHCARE CAPITOL CITY	DC													
95022	TRANSITIONS HEALTHCARE CAPITOL CITY	2425 25TH STREET SE	DC	20020	12/1/14	Fire Safety	K	130	Other fire safety features required by fire safety codes.	D	Deficient, Provider has date of correction	1/20/15	1	Y	N
95022	TRANSITIONS HEALTHCARE CAPITOL CITY	2425 25TH STREET SE	DC	20020	11/5/13	Fire Safety	K	130	Other fire safety features required by fire safety codes.	E	Deficient, Provider has date of correction	2/11/14	2	Y	N
95022	TRANSITIONS HEALTHCARE CAPITOL CITY	2425 25TH STREET SE	DC	20020	#####	Fire Safety	K	130	Other fire safety features required by fire safety codes.	E	Deficient, Provider has date of correction	11/30/12	3	Y	N

12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15

12/1/15
12/1/15
12/1/15
12/1/15
12/1/15
12/1/15